

Yamaha USB-MIDI Driver V1.2.0 for Mac OS X Release Notes

Main Revisions and Enhancements

V1.1.1 to V1.2.0

- Changed the specification so that MIDI Port names did not show any device names. You can update the Port names of the current device by following procedure.

1. Remove the device(s) from the computer.
2. Confirm whether the using device being used is registered to the "MIDI Devices" of the "Audio MIDI Setup." If the device is registered, remove the device from the "MIDI Devices."
3. Connect the device again to the computer.

NOTE:

If you want to use the previous Port names, set the "Include device name in port name (old style)" to "on" in the "Yamaha USB-MIDI" of the "System Preferences," then execute the procedure above.

- The MIDI Patch function and the MIDI Thru function have been removed.
- Minor bug fixes.

Legacy Updates

V1.1.0 to V1.1.1

- A problem in which the driver did not operate properly in some language environments has been corrected.
- Minor bug fixes.

V1.0.4 to V1.1.0

- Support for Macintosh computers using Intel processors has been added.

V1.0.3 to V1.0.4

- Problems in which the MIDI driver occasionally hangs up during transmission and reception of MIDI data when using a dual CPU Macintosh have been corrected.

V1.0.1 to V1.0.3

- Handling of system exclusive message errors has been improved.

V1.0.0 to V1.0.1

- Problems in opening the audio port of the UW500/UW10 when using Emagic Logic have been corrected.

V1.0.0b1 to V1.0.0

- Design of icons has been changed.

Company and product names that appear in this document are the trademarks or registered trademarks of their respective companies.

(C) 2009 Yamaha Corporation All Rights Reserved.